

# RECLAIMING SCREENS WITH CHEMICALS FOR SCREENPRINTING

## USE:

COLD WATER (with a sponge)	to remove	Hunt Speedball drawing fluid and Acrylic Inks (don't let ink dry on screen – clean when still wet)
MR. CLEAN (scrub screen with fingernail brush, let soak and then blast with high pressure water spray)	to remove	Hunt Speedball Screen Filler (the red stuff)
ULANO STENCIL REMOVER NO. 4 OR BLEACH (scrub, soak, blast)	to remove	Ulano TZ (or diazo based) photo emulsion (the green stuff)
DENATURED ALCOHOL (scrub and rinse or blast if necessary)	to remove	Photo emulsion residue or halo
ACETONE (scrub, blast)	to remove	Dried bits of acrylic ink
MR. CLEAN SOFT SCRUB (scrub, rinse)	to prepare	the surface of a new screen